


Users manual/Használati útmutató Big Fat Mother



1. External power supply connector
2. Tube preamp bypass switch
3. Tube preamp gain pot
4. Tube socket with tube
5. FX loop Return 6.3mm jack connector
6. FX loop Send 6.3mm jack connector
7. DC 9V/1A centre negative 5.5/2.1mm power connector
8. Output 6.3mm jack connector to amplifier
9. Input 6.3mm jack connector for instruments
10. DC 12V/2A (total load) centre negative 5.5/2.5mm power connector for Hunor Tube Pedals.
Connecting two pieces of tube per connector allowed.

1. Külső tápegység csatlakozó
2. Csöves előfok KI/BE kapcsoló
3. Csöves előfok erősítés szabályzó potenciométer
4. Elektroncső
5. Effekthurok Return 6.3mm jack csatlakozó
6. Effekthurok Send 6.3mm jack csatlakozó
7. DC 9V/1A center negatív 5.5/2.1mm tápcsatlakozó
8. Kimenet az erősítőhöz, 6.3mm jack csatlakozó
9. Bemeneti csatlakozó a hangszerek számára, 6.3mm jack csatlakozó
10. DC 12V/2A (összterhelhetőségű) center negatív 5.5/2.5mm tápcsatlakozó a Hunor csöves pedálok részére. Csatlakozónként 2 db cső meghajtása megengedett.



Copyright 2015 Hunor Tube Pedals

